

Refridge Flash Fire

Safety Alert

Issue #: 1-2016

Enform

Enform is the health and safety association for Canada's upstream oil and gas industry. We provide leading health and safety training, programs and services, touching the lives of hundreds of thousands of workers each year. We are dedicated to the continuous improvement of safety with a vision of eliminating work-related incidents or injuries in the upstream oil and gas industry.

An Industry Product

This document was developed by industry for industry. Working collaboratively, Enform works with the submitting organization representative in developing these documents to improve the industry's hazard awareness. Canada's leading oil and gas industry trade associations support the use of shared information to help companies of all sizes improve performance.

Disclaimer

This document is intended to be flexible in application and provide guidance to users rather than act as a prescriptive solution. Recognizing that one solution is not appropriate for all users and situations, it presents accepted guidance that generally apply to all situations. While Enform believes that the information contained herein is reliable under the conditions and subject to the limitations set out, Enform does not guarantee its accuracy. The use of this document or any information contained will be at the user's sole risk, regardless of any fault or negligence of Enform and the submitting organization.

Copyright/Right to Reproduce

Copyright for this document is held by Enform, 2016. All rights reserved. Enform encourages the copying, reproduction and distribution of this document to promote health and safety in the workplace, provided that Enform is acknowledged. However, no part of this publication may be copied, reproduced or distributed for profit or other commercial enterprise, nor may any part be incorporated into any other publication, without written permission of Enform.

For more information on this event, please contact: safety@enform.ca

Description of Incident:

An operator recording equipment readings (logging) at the refrigeration (refridge) building observed scorch marks on the exterior of the building and glycol/steam venting out of a pressure release vent on the still column. The scorch marks were located above the reboiler unit as well as on the reboiler unit itself and the associated piping and insulation.



Scorched Exterior of Refridge Building



Scorched Piping/Insulation Under Reboiler

What Caused It?

A buildup of condensate in the system.

- The reboiler is designed to flash off water and any associated hydrocarbons, including benzene, by heating the glycol to approximately 120°C.
- If hydrocarbons are present at a sufficient volume in the glycol, a hydrocarbon-glycol foam can form on the surface of the glycol within the glycol accumulator.
- In this case the buildup was such that it triggered the pressure release vent, releasing hydrocarbon vapours that subsequently ignited.
- The precise cause of ignition is unknown, but may have been the hot reboiler exhaust stack.

By industry, for industry





Contributing Factors Included:

- Failure to maintain a glycol/condensate interface in the Low Temperature Separator. Personnel felt that glycol skimming was not required because the location no longer produced condensate.
- Operators were not trained in maintaining the interface in the Low Temperature Separator.
- The pressure release vent on the still column was undersized.

Corrective/Preventative Actions:

- The pressure release vent was replaced with a properly fit for purpose design.
- Operators received additional training in the maintenance of glycol refrigeration systems.
- Operators will skim the glycol accumulator on a regular basis. This task may have the potential for operator hydrocarbon exposure (namely benzene), therefore an exposure assessment was recommended.
- Sampling of the gas and glycol will be conducted on a regular basis.

By industry, for industry

