

# Airbag Deployment Obstruction

**Safety Alert**

Issue #:10-2016

**Enform**

Enform is the health and safety association for Canada's upstream oil and gas industry. We provide leading health and safety training, programs and services, touching the lives of hundreds of thousands of workers each year. We are dedicated to the continuous improvement of safety with a vision of eliminating work-related incidents or injuries in the upstream oil and gas industry.

**An Industry Product**

This document was developed by industry for industry. Working collaboratively, Enform works with the submitting organization representative in developing these documents to improve the industry's hazard awareness. Canada's leading oil and gas industry trade associations support the use of shared information to help companies of all sizes improve performance.

**Disclaimer**

This document is intended to be flexible in application and provide guidance to users rather than act as a prescriptive solution. Recognizing that one solution is not appropriate for all users and situations, it presents accepted guidance that generally apply to all situations. While Enform believes that the information contained herein is reliable under the conditions and subject to the limitations set out, Enform does not guarantee its accuracy. The use of this document or any information contained will be at the user's sole risk, regardless of any fault or negligence of Enform and the submitting organization.

**Copyright/Right to Reproduce**

Copyright for this document is held by Enform, 2016. All rights reserved. Enform encourages the copying, reproduction and distribution of this document to promote health and safety in the workplace, provided that Enform is acknowledged. However, no part of this publication may be copied, reproduced or distributed for profit or other commercial enterprise, nor may any part be incorporated into any other publication, without written permission of Enform.

For more information on this alert, please contact: [safety@enform.ca](mailto:safety@enform.ca). To view other safety alerts please visit [enform.ca](http://enform.ca).

**Description of Incident:**

During a recent motor vehicle incident the side airbag was prevented from deploying properly. No injuries were sustained in this incident. Many of today's vehicles have side impact airbags installed on the outside section of the front seats to complement side impact curtains in the event of a side impact collision.



View of partially deployed airbag



View of hook and loop closure opening on seat cover

**What Caused It?**

An aftermarket seat cover obstructed the deployment of the airbag. In this case, the seat covers were installed in reverse: the driver's seat cover was installed on the passenger side and the passenger's seat cover was installed on the driver side. This placed the hook and loop closure opening on the wrong side of the seat, preventing the airbag from properly deploying.

**Corrective/Preventative Actions:**

- Drivers were required to inspect their seat covers for proper installation and implement any corrective actions

By industry, for industry

